



LightSpur™ RX

USAGE INSTRUCTIONS

- >> Press and hold power button for 2 – 3 seconds to turn on.
- >> Once on, double-click the button at any time to cycle through color options.
- >> Single-click the button at any time to cycle through lighting modes.
- >> Press and hold power button for 2 – 3 seconds to turn off.

TO RECHARGE:

- >> Plug supplied USB cord in to a USB power source (200mA minimum) and then plug gently in to the covered charge port on the back of the unit. A red LED will light up to indicate charging is occurring and a green light indicates the LightSpur RX is fully charged.
- >> Charge time is 3 hours for a fully depleted battery.
- >> When fully charged, unplug LightSpur RX from USB power supply, return port cover gasket to original position and store charger cord until next use.

